

Imray Correction Notice

16 May 2012

ICC34-1

Chart C34 WGS 84

Edition Dec 2009

Date of printing Dec 2009

The following corrections should be noted:

1 Tréguier (Plan I)

Mariners should be aware that the charted dredged areas on this plan no longer exist, and that depths may be 1–2m less than shown. (ILNW 130/10)

2 Tréguier (Plan I)

Delete anchorage and visitors' mooring, centred on 48°47'·41N 3°13'·49W.

A new pontoon exists in position 48°47'·39N 3°13'·44W. (ILNW 131/10)

3 Paimpol (Plans J & N)

Amend range of Lt from 14M to 10M in 48°47'·07N 3°02'·74W (ILNW 330/10)

4 Les Héaux de Bréhat (Main chart & Plan H)

Insert A/S at **La Jument des Héaux** Q Lt buoy in 48°55'·33N 3°08'·04W (ILNW 4/11)

5 Baie de Saint-Brieuc

Delete drying wk in 48°37'·11N 2°46'·80W (ILNW 30/11)

6 Baie de Saint-Brieuc

Insert dangerous wk sym, plus assoc. lgd *PD*, in 48°43'·30N 2°47'·80W (ILNW 354/11)

7 Ile de Bréhat southwards (Main chart, Plan J & Plan L)

Amend Lt at Men-Joliguet bn to Fl(2)WRG.6s6m11–8M in 48°50'·12N 3°00'·20W (ILNW 180/12)